Docket No. SA-537
Exhibit No. 6-AB

NATIONAL TRANSPORTATION SAFETY BOARD

Washington, D.C.

FAA Presentation I Airplane Cabin Crashworthiness & Occupant Protection

(12 Pages)

Occupant Protection Requirements

Presented to: NTSB

By: Jeff Gardlin, Transport Airplane Directorate

Date: December 11, 2013




Accident Prevention vs. Mitigation

- Primary safety objective accident prevention
- Secondary Hazard mitigation in an accident event
- Accident rate is extremely low
- Traffic growth means even a low rate will result in some accidents



Trends






US Fleet 9 year Moving Average (DOT/FAA/TC-13/46)



Trends

Transport Category and Select 'Large' Airplanes



<u>Worldwide</u> Fatalities—All Accidents and Survivable Accidents (DOT/FAA/AR-10/16--updated)




Elements of Occupant Survivability

Speed of **Occupant** protection **Egress** § 25.807, § 25.561, § 25.809, § 25.562, § 25.811, § 25.785, § 25.812 § 25.787, § 25.813, § 25.789 § 25.815 **Time Available** for Egress § 25.853



FAA Occupant Safety Advancements





Major Occupant Safety Initiatives

Extend Egress Time:

- Low Heat Release Interiors (1986 Amdt. 25-61)
- Fire resistant seat cushions (1984 Amdt. 25-59)
- Burnthrough resistant insulation (2003 Amdt. 25-111)
- Heat resistant escape slides (1983 TSO C69a)

Speed of Egress

- Floor proximity lighting (1983 Amdt. 25-58)
- Access to type III exits (1992 Amdt. 25-76)
- Escape slide evacuation rate improvements (1999 TSO C69c)



Major Occupant Safety Initiatives

Occupant Protection

- Dynamic testing of seats/Quantitative Occupant protection criteria (1988 Amdt. 25-64)
- Increased static load factors (1988/1997 Amdt. 25-64/97)

Other In-Flight Fire Safety Requirements:

- Lavatory smoke detectors
- Cargo compartment fire suppression
- Thermal/acoustic insulation flammability resistance



Examples: 100% Survivability 2005-2013





Summary

- Accidents extremely infrequent, but will occur
- Accidents more survivable than ever
- Recent experience indicates that regulatory safety enhancements mitigate hazards and improve survivability



Regulatory Reference Information

- Floor Proximity Emergency Escape Path Marking: October 1984, Amendments 25-58, 121-183
- Improved Flammability of Seat Cushions: October 1984, Amendments 25-59, 29-23, 121-184
- Improved Interior Materials:
 July 1986, Amendments 25-61, 121-189
- "16G" Seats: May 1988,
 Amendment 25-64; October 2005, Amendments 121-315

- Improved Access to Type III
 Exits: May 1992,
 Amendments 25-76, 121-228
- Thermal/Acoustic Insulation: July 2003, Amendments 25–110, 91– 275, 121–289, 125–43, 135– 85
- Escape Slide Performance:
 June 1983, Technical
 Standard Order C69a;
 August 1999, Technical
 Standard Order C69c



Accident References

- Air France A340-300 in Toronto, Canada, 8/2/05; 297 passengers and 12 crew
- British Airways 777-200 in London, England, 1/17/08; 136 passengers and 16 crew
- Continental Airlines 737-500 in Denver, Colorado, 12/20/08;
 110 passengers and 5 crew
- American Airlines 737-800 in Kingston Jamaica, 12/22/09;
 148 passengers and 6 crew

- Merpati 737-300 in Manokwari-Rendani Airport Indonesia, 4/13/10: 103; passengers and 7 crew
- 737-800 China Airlines in Okinawa8/20/07: 157 passengers and 8 crew
- Lion Air 737-800, Bali Indonesia 4/13/13: 101 passengers and 8 crew

